


ARC TERRA
CONSULTING, INC
 212 E. 51st Ave, Anchorage, AK. 99503
 Office (907) 868-3791, Fax (907) 868-3793



SOILS PERCOLATION TEST


Performed for: **Shadowoods, LLC**

Date Performed: **05/01/2008**

Project: **Primrose Pointe Phase II Lot 49, Block 1**

TEST HOLE # **TH 08-49**

Depth
(Feet)



Org/OL

SW loose/sluffing

B.O.H. 18'

**INSITU MATERIAL
SUITABLE AS FILTER**

**SEE ATTACHED SITE PLAN
FOR HOLE LOCATION**

Was Ground water encountered? **NO** What depth? **NA**

Depth to water after monitoring? **DRY** Date? **5/15/08**

Reading	Date	Gross Time	Net Time	Depth to Water	Net Drop
1					
2					
3					
4					
5					
6					
7	VISUAL 125 SF/BDRM BELOW 2'				
8					
9					
10					
11					
12					
*					

Percolation Rate _____(min/in) Perc Hole Diameter____

Test Run Between ____feet and ____feet

I, Kenneth M. Duffus, certify that this test was performed in accordance with all State guidelines in effect on this date.