


**ARC TERRA**  
**CONSULTING, INC**  
 212 E. 51<sup>st</sup> Ave, Anchorage, AK. 99503  
 Office (907) 868-3791, Fax (907) 868-3793



**SOILS PERCOLATION TEST**


Performed for: **Shadowoods, LLC**

Date Performed: **05/01/2008**

Project: **Primrose Pointe Phase II Lot 51, Block 1**

TEST HOLE # **TH 08-51**

Depth  
(Feet)



**B.O.H. 18'**

**INSITU MATERIAL  
 SUITABLE AS FILTER**

**SEE ATTACHED SITE PLAN  
 FOR HOLE LOCATION**

Was Ground water encountered? **NO**      What depth? **NA**  
 Depth to water after monitoring? **DRY**      Date? **5/15/08**

| Reading | Date | Gross Time | Net Time | Depth to Water | Net Drop |
|---------|------|------------|----------|----------------|----------|
| 1       |      |            |          |                |          |
| 2       |      |            |          |                |          |
| 3       |      |            |          |                |          |
| 4       |      |            |          |                |          |
| 5       |      |            |          |                |          |
| 6       |      |            |          |                |          |
| 7       |      |            |          |                |          |
| 8       |      |            |          |                |          |
| 9       |      |            |          |                |          |
| 10      |      |            |          |                |          |
| 11      |      |            |          |                |          |
| 12      |      |            |          |                |          |
| 13      |      |            |          |                |          |
| 14      |      |            |          |                |          |
| 15      |      |            |          |                |          |
| 16      |      |            |          |                |          |
| 17      |      |            |          |                |          |
| 18      |      |            |          |                |          |
| *       |      |            |          |                |          |

**VISUAL 125 SF/BDRM  
 BELOW 3'**

Percolation Rate \_\_\_\_\_ (min/in) Perc Hole Diameter \_\_\_\_\_  
 Test Run Between \_\_\_\_\_ feet and \_\_\_\_\_ feet

I, Kenneth M. Duffus, certify that this test was performed in accordance with all State guidelines in effect on this date.