

**ARC TERRA**  
**CONSULTING, INC**  
 212 E. 51<sup>st</sup> Ave, Anchorage, AK. 99503  
 Office (907) 868-3791, Fax (907) 868-3793



**SOILS PERCOLATION TEST**

Performed for: **Shadowoods, LLC**


Date Performed: **05/01/2008**

Project: **Primrose Pointe Phase II Lot 52, Block 1**

TEST HOLE # **TH 08-52**

Depth  
(Feet)

**SEE ATTACHED SITE PLAN  
FOR HOLE LOCATION**



Was Ground water encountered? **NO**      What depth? **NA**  
 Depth to water after monitoring? **DRY**      Date? **5/15/08**

Reading	Date	Gross Time	Net Time	Depth to Water	Net Drop
1					
2					
3					
4					
5					
6					
7	<b>VISUAL 125 SF/BDRM BELOW 5'</b>				
8					
9					
10					
11					
12					
*					

**B.O.H. 19'**  
**INSITU MATERIAL  
SUITABLE AS FILTER**

Percolation Rate \_\_\_\_\_ (min/in) Perc Hole Diameter \_\_\_\_\_  
 Test Run Between \_\_\_\_\_ feet and \_\_\_\_\_ feet

I, Kenneth M. Duffus, certify that this test was performed in accordance with all State guidelines in effect on this date.